

Rockwell **service bulletin** No. SB-AG-7

International

P.O. BOX 3090 ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

Service Bulletin No. SB-AG-7
10 September 1975

IMPROVE HOPPER LATCH

MODEL AFFECTED: MODEL S-2R, SERIAL NO'S 2072 THRU 2173 AND 5001 THRU 5082.

REASON FOR PUBLICATION: To prevent inadvertent opening of hopper door in flight.

COMPLIANCE: Upon receipt of this Service Bulletin.

NOTE

IF ANY PROBLEMS ARE ENCOUNTERED WHILE COMPLYING WITH THIS SERVICE BULLETIN. CONTACT ROCKWELL INTERNATIONAL, GENERAL AVIATION DIVISION, CUSTOMER SERVICE DEPARTMENT, BETHANY, OKLAHOMA 73008.

BY WHOM WORK WILL BE ACCOMPLISHED: Owner operator or A & P mechanic.

APPROVAL: FAA DER Approved.

ESTIMATED MAN HOURS: One (1) Hour.

PARTS DATA: Parts required to accomplish the modification specified by this Service Bulletin are furnished, at no charge, by Rockwell International, General Aviation Division, Spare Sales Department, Bethany, Oklahoma 73008.

**SERVICE BULLETIN NO. SB-AG-7
10 SEPTEMBER 1975**

<u>QTY</u>	<u>PART NO.</u>	<u>DESCRIPTION</u>
1 ea.	54425	Latch Tension Kit
	CONSISTING OF:	
	1 12538	Spring
	1 40019	Bolt
	1 80575	Nut
	2 10866	Washer
	1 96092	Installation Instructions
1 ea.	Service Bulletin No. SB-AG-7	Instructions
1 ea.		Compliance Card

SPECIAL TOOLS: NONE

ACCOMPLISHMENT INSTRUCTIONS:

1. Open hopper door to gain access to rear hopper latch.
2. Install Kit per Transland Installation Instructions.
3. Fill out and mail Compliance Card.

ELECTRICAL LOAD: NOT APPLICABLE

WEIGHT AND BALANCE: NO CHANGE

PUBLICATIONS AFFECTED: The Illustrated Parts Catalog will incorporate the change required by this document at the next scheduled change revision.

RECORD COMPLIANCE: Make appropriate entry in airplane maintenance records as follows: Service Bulletin No. SB-AG-7, dated 10 September, 1975, entitled "Improve Hopper Latch" accomplished _____ (date) _____.