

# Rockwell service letter No. SL-AG-35

## International

P.O. BOX 3090 ALBANY, GEORGIA 31706-3090 PHONE 229/883-1440 FAX 229/439-9790

---

---

**Service Letter No. SL-AG-35**  
**March 31, 1964**

### **CORROSION PROBLEM WHEN USING HIGHLY CORROSIVE MATERIALS**

**APPLICABILITY:** ALL S-2 models, Serial Number 1003 & SUBS

All operators of Snow S-2 Aircraft are reminded to clean their aircraft frequently when using very corrosive materials like certain fertilizers. Particular attention should be given to the center splice fitting of wing and nearby structural parts. There is a possibility that corrosion can damage the aluminum wing spars and center fittings so severely that replacement would be necessary. This has already occurred on one relatively new, low time airplane.

This service letter is issued solely to make operators aware of the extreme damage which can result when corrosion is not controlled.